

Subject: Automatic Transmission Shifting Delayed Upshifts	g, Erratic, Harsh or Group: 01 Number: 98–05
Model(s): 4 Speed Auto. Trans. with Digimat 2.1 TCM	1995 ➤ see below Date: Apr. 21, 1998
Supersedes	s T.B. Group 01 number 97–01 dated Jan. 8, 1997
	Condition
	Transmission shifting is erratic, harsh or holds shifts too long (delayed upshifts) with no Diagnostic Trouble Codes (DTC) stored in DTC memory.
	Condition is normally caused by improper throttle angle setting.
	Only occurs up to EPROM level 4066.
	Service
	If any of these conditions exist, check EPROM level and throttle angle setting (if Eprom level is below 4066) as follows:
	 Connect VAG 1551 Scan Tool.
	 Switch ignition ON (do not start engine).
Rapid data transfer HELP	Indicated on display:
Insert address word XX	 Press buttons -0- and -2- to select address word "02 Transmission Electronics".
Rapid data transfer Q	Indicated on display:
02 Transmission electronics	Press -Q- button to confirm input.
01M927733BB AG4 Gearbox 01M 2029 Coding 00000 WSC 00000	Indicated on display: Example shows EPROM level as 2029.
	- Press the \rightarrow button to advance program.
Rapid data transfer HELP	Indicated on display:
Insert address word XX	 Press buttons -0- and -8- to select function 08 "Read measuring value block".
Rapid data transfer Q	Indicated on display:
08 Read measuring value block	 Press -Q- button to confirm input.
	(Cont. on Page 2)
C	1

<u>1</u>



Reading measuring value block Input display group number XXX

Read measuring value block $1 \rightarrow$ P0.21 V0%00000111

Indicated on display:

- Press buttons -0-, -0- and -1- (to input display group 001).
- Press -Q- button to confirm input.

Indicated on display:

- Without pressing accelerator pedal, print screen.

Note:

While performing the following steps press the accelerator pedal slowly, do not release the pedal.

- These 2 displays show incorrect throttle angle setting readings and should be used as examples only.
 - While observing VAG 1551 display press accelerator pedal until third display field reads 50%, then print screen.
 - While observing VAG 1551 display continue pressing accelerator pedal until third display field reads 95%, then print screen.
 - Continue pressing accelerator pedal to the pedal stop while observing the fourth digit in the fourth channel.
- Fourth digit must change from 0 to 1, indicating kickdown, hold for approx. 5 seconds (sets throttle angle setting).
 - Release accelerator pedal fully and press \rightarrow button.

(Cont. on Page 3)

Example of incorrect basic setting readings				
Read measuring value block			1 →	
Р	1.87 V	50%	00000111	
Read measuring value block		$1 \rightarrow$		
Р	3.45V	95%	00000111	
			01-A008	

Read me	ad measuring value block		$1 \rightarrow$
Р	4.35 V	100%	00010111

С



Example of correct basic setting readings

Read measuring value block			$1 \rightarrow$
Р	0.19 V	0%	00000111
Р	2.30 V	50%	00000111
Р	4.29 V	95%	00000111
Ρ	4.35 V	100%	00010111

01-A008





- Repeat procedure again.
- Compare first test voltage readings in second display field and throttle angle percentages in 3rd display field with readings from second test.

If readings are not within 0.05 volts, then throttle angle setting was not correct. Perform the following:

- Switch ignition OFF.

Verify that vehicle is equipped with a Digimat 2.1 TCM.

TCM, identification

- Lift rear seat.
- Locate and inspect TCM electrical connector receptacle.
- The Digimat 2.1 TCM electrical connector receptacle (boxed area) is made of black plastic (NOT Aluminum).

Note:

Whenever a Digimat 2.0 TCM is replaced with a Digimat 2.1 TCM (with EPROM level below 4066), the resistor wire modification below MUST be performed.

DO NOT perform procedure if the electrical connector receptacle is made of aluminum.

DO NOT perform procedure if EPROM level of Digimat 2.1 TCM is above 4066.

Resistor wire, installing

- Disconnect 68 pin connector from TCM.
- Cut tie wrap at end of connector and remove cover from connector by depressing tab with small screwdriver while pushing cover in direction of -arrow-.

(Cont. on Page 4)

С









 Twist stripped end of resistor wire with end of (gray/green) wire coming from harness, install butt-splice and crimp as shown.



- Crimp remaining end of gray/green wire (from TCM connector end into other end of butt-splice as shown).
 - Re-tape wiring harness.
 - Reinstall TCM connector cover and install new tie-wrap.
 - Reinstall connector onto TCM.
 - Verify throttle angle setting using Function 08 display group 001 ⇒ page 1 (IMPORTANT! kickdown switch activation must be verified during throttle angle setting).

When procedure applies to vehicles within the New Vehicle Limited Warranty, use the following:

Part Identifier:	3730	
Labor Operation:	3730510	50TU