

Technical Bulletin

| Subject: | Airbag System, Use of Stabilant 22A on Electrical Connections OK | | Group: 69 Number: 95–03 |
|-----------|---|---|--|
| Model(s): | All with Airbag Systems | m.y. All | Date: Sept. 11, 199 |
| | | Service | |
| | | When following Airbag diagnostic procedures outlined in section 01 of the appropriate Repair Manual: Be sure to check wiring connections as outlined in the "Correction" column of the diagnostic troubleshooting procedures. | |
| | | | |
| | | When a procedure requires separation or replacement of a terminal, always apply contact enhancer, Stabilant 22A, Part No: ZVW 186 001, to the terminal. Refer to Technical Bulletin Group 97, number 95–03, dated Apr. 11, 1995. | |
| | | <i>Caution!</i> <i>Part numbers are for reference only.</i> <i>Always check with your Parts Dept.</i> <i>for the latest parts information.</i> | |
| | | •• | of the contact enhance nections and retest th |
| | | necessary, Stabilant | arness replacement i 22A should be applied t connecting the harness. |
| | | • | expense of the Stabilar ion 97A1000 5TU to you |
| | | | et the Battery Ground working on the airbag |

С