



**Important!**

Please give copies to all  
your VW Technicians

# Technical Bulletin

## Vehicle Delivery Information

---

Subject: **Radio, Inoperative at Pre-Delivery Inspection (PDI)**

Group: **00**

Number: **00-01**

Model(s): **EuroVan**

**2000**

Date: **Jan. 13, 2000**

---

### Condition

Radio does not operate at PDI after installing fuse S21.

May be due to disconnected black connector on back of radio.

This condition may be identified by a sticker (red dot ) placed on the radio Scan button.

### Service

During PDI, after installing fuse S21, if radio does not operate:

- Remove radio and connect black connector to back of radio.
- Set radio code and check operation of radio/cassette and CD (if applicable) as outlined in the Technician PDI checklist.

**When procedure applies to vehicles within the New Vehicle Limited Warranty, use the following:**

**Damage Code: 9135 40 000 1**

**Labor Operation: 9135110 25TU**

---

**C 00-00-01**

© 2000 Volkswagen of America, Inc.