



Technical Bulletin

Subject: **Battery, Charging Precautions**

Group: **27**

Number: **95-01**

Model(s): **All**

All

Date: **Jan. 13, 1995**

Condition

Inoperative Engine Control Modules (ECM) due to improper battery charging or starting procedures.

Service

- Always follow battery charging procedures as outlined in the applicable Repair Manual for the respective model.

To avoid damage to the ECM, the following additional precautions must also be taken:

- Ignition must be switched off.
- Do not start engine while charging battery.
- Do not use battery chargers or boosters that exceed 16 volts.
- Do not disconnect ECM with the ignition switched on.
- Ensure that ECM connectors are secure.

Caution !

Follow the above instructions to avoid damage to the ECM.