



# Technical Bulletin

Subject: **Automatic Transmission Fluid (ATF) Seeping From Final Drive Breather Vent**

Group: **39**

Number: **97-01**

Model(s): **All with 4 Speed Automatic Transmission (AG4)**

Date: **Sept. 12, 1997**

## Condition

ATF fluid seeping from final drive breather vent.

## Production

- Beginning August 26, 1996, transmission final drive units were filled with final drive oil Part No: **G 052 145 S2**
- From December 21, 1994 to August 25, 1996 Automatic transmission final drive units were filled with VW (ATF).

On final drive units filled with ATF, (in some instances) ATF may seep out of the final drive breather vent (arrow -A-).


## Service

If this condition exists:

### Note:

**Only transmissions within build date range 21124 ➤ 25086. (see transmission identification below) are affected.**

- Inspect transmission build date (arrow -B-).



Example:	CKX	21	12	4
	Transmission code letters	Day	Month	Year

If transmission is within build date, final drive is filled with ATF and fluid is seeping from final drive breather vent perform the following:

- Remove final drive cover, drain ATF, reinstall cover (always use new gasket).

(Cont. on Page 2)



# Technical Bulletin

---

- Refill final drive with G 052 145 S2 final drive oil (see appropriate Repair Manual).

**Note:**

- ***Do not intermix ATF and G 052 145 S2 oil!***
- ***If final drive fluid must be replaced, only use G 052 145 S2 oil (do not fill with ATF)!***
- ***If topping off final drive fluid on transmissions built prior to or after build dates listed, only use G 052 145 S2 oil.***
- ***You may top off final drive fluid with ATF, only if final drive is filled with ATF and no fluid is coming out of breather vent.***

When procedure applies to vehicles within The New Vehicle Limited Warranty and adheres to Warranty Policy guidelines, use the following:

Part Identifier: 3920

Labor Operation: 3920510 80 TU