



Service Circular

Tools - Equipment

**Subject: VR6 EUROVAN TOOL PACKAGE
AUTOMATIC TOOL SHIPMENT AT-151
MINIMUM REQUIREMENT - USA
VOLKSWAGEN (NON-WINNEBAGO) DEALERS**

**Number: V98-05
Date: 06-MAR-98**

With the introduction of the new 98 MY Eurovan with VR6 engine, a number of special tools are required. AT-151 contains five tools which are used when repairing the Eurovan VR6 engine or removal of the O1P automatic transmission. A breakdown of these tools are listed on the attachments along with price and application information.

Every Volkswagen (non-Winnebago) Dealer will be shipped one AT-151 (VR6 Eurovan Package), freight prepaid from Zelenda Automotive Inc. and **invoiced from Equipment Solutions**. AT-151 (VR6 Eurovan Tool Package) will be shipped to the attention of the Volkswagen Service Manager. Shipments will commence March 30 1998, and conclude that same week.

If you wish to order additional AT-151 Special Tool Packages, please notify **Equipment Solutions** at (800-892-9650) before March 30, 1998. Individual pieces of the package may be ordered from Equipment Solutions after the automatic shipment takes place. All shipping and billing inquiries should be directed to **Equipment Solutions**.

AT-151 VR6 EUROVAN TOOL PACKAGE

<u>Tool Number</u>	<u>Description</u>
3406	Counter-Hold Tool
3407	Bracket
3408	Engine Support
10-222A6	Adapter
10-222A7	Adapter

<u>PACKAGE QTY</u>	<u>FRANCHISE TYPE</u>	<u>DEALER PRICE</u>
FIVE TOOLS	VOLKSWAGEN: NON-WINNEBAGO DEALERS ONLY!	\$ 385.00



Service Circular

Tools - Equipment

If you require additional tools or wish to order tools **after the automatic shipment**, the ordering information is as follows:

<u>Tool No.</u>	<u>Description</u>	<u>Dealer Price</u>	
3406	Counter-Hold Tool	\$ 75.80	
3407	Bracket	\$ 34.30	
3408	Engine Support	\$150.00	
10-222A6	Adapter	\$116.35	
10-222A7	Adapter	\$ 34.50	
		\$410.65	AT-151 PKG.= \$385

3406

Counter-Hold Tool


Repair Group 10

Engine-Assembly

Used to Remove the Vibration Damper on Eurovan with VR6 Engine. Also used when replacing Crankshaft Oil Seal, Flywheel, and adjustment of Valve timing.

Volkswagen Eurovan (VR6 engine)

T03 406 000 10 ZEL



3407

Bracket


Repair Group 10

Engine-Assembly

Used for Removal and Installation of Automatic Transmission OIP. Used in conjunction with 10-222A Engine Support Bridge, 10-222A6 Adapter and 10-222A7 Adapter.

Volkswagen Eurovan (VR6 engine)

T03 407 000 10 ZEL



3408

Engine Support



Service Circular

Tools - Equipment


Repair Group 10

Engine-Assembly

Used to Remove/Install VR6 Engine on Volkswagen Eurovan.

Volkswagen Eurovan (VR6)

T03 408 000 10 ZEL



10-222A6

Adapter


Repair Group 10

Engine-Assembly

Used for Removal and installation of Automatic Transmission O1P. Used in conjunction with 10-222A Engine Support Bridge, 10-222A7 Adapter and 3407 Bracket.

Volkswagen Eurovan (VR6 engine)

T10 222 A60 10 ZEL



10-222A7

Adapter

Repair Group 10

Engine-Assembly

Used for Removal and installation of Automatic Transmission O1P. Used in conjunction with 10-222A Engine Support Bridge, 10-222A6 Adapter and 3407 Bracket.

Volkswagen Eurovan (VR6 engine)

T10 222 A70 10 ZEL

