



Service Circular

Warranty

Subject: Loose or Missing Fuel Cap

Number: VWA-01-03

Date: Feb. 15, 2001

For a customer concern that the "Malfunction Indicator Lamp" (MIL) is illuminated and a diagnostic trouble code (DTC) is present for a gross or small evaporative emission (EVAP) system leak, the following policy is effective immediately. **If it is determined that the cause of the EVAP system leak is a loose or missing fuel cap**, and the vehicle is within the parameters of the Limited New Vehicle Warranty period, Volkswagen will reimburse you 20 time units for diagnosis. This diagnostic payment is for a "NoTrouble Found" (NTF) condition, not a defect in material or workmanship, and may be claimed one-time only. Please educate the customer regarding a loose fuel cap and illumination of the MIL and advise them that this concern will be covered under warranty one-time only.

Claim Processing:

Claim Type: W2
Damage Code: 2005 66 000 1
Labor Operation: (Claim one of the following, one-time only)
For VAS 5051: 01290001 20 Time Units
For VAG 1551: 01300001 20 Time Units

Diagnosis time must be punched on and off separately and a copy of the 5051/1551 printout must be attached to the repair order hard copy.