



Technical Bulletin

Subject: **DTC Readout 00735, Incorrect**

Group: **01**

Number: **95-07**

Model(s): **All with 2.8L VR6 (Engine Code AAA)**

Date: **Oct. 11, 1995**

Condition

Incorrect DTC 00735 can be stored by some Engine Control Modules when a questionable condition exists in the EVAP purge system.

Correct DTC is:

01247 4343

EVAP Canister Purge Regulator
Valve-N80

Short to B+ or

Open/short circuit to Ground(GND)

Service

If DTC 00735

Recirc. Flap Mtr. Pos. Sensor - G143

Open/Short circuit to ground

Sporadic DTC

is stored:

- Refer to DTC 01247/4343 in the DTC Table of the respective Repair Manual.
- Make any needed diagnosis/repairs in accordance with DTC 01247/4343.

When the electrical diagnosis procedure applies to vehicles within warranty add Labor Operation 24B2000 80 TU to your warranty claim: